The table below lists the details of the trees to be removed in Highbury Road, Mount Waverley/Burwood.

No	Location	Species	Condition Assessment
1.	1/14 Highbury Road	Eucalyptus scoparia	Lopsided form, epicormic canopy, < 2 Years ULE.
2.	16 Highbury Road	Eucalyptus scoparia	Most of the canopy is epicormics, < 2 Years ULE.
3.	24 Highbury Road	Eucalyptus scoparia	Poor amenity, wit< 2 Years ULE.
4.	2 Barnes Avenue	Hibiscus sp.	Shrub, not a street tree.
5.	40 Highbury Road	Callistemon salignus	Blocking street light, clearance would remove 30% canopy.
6.	76 Highbury Road	Eucalyptus scoparia	Epicormic crown, < 2 Years ULE.
7.	88-94 Highbury Road	Eucalyptus scoparia	Canopy is 1 branch plus epicormic, insect infestation in over 50% of canopy, < 2 Years ULE.
8.	96-98 Highbury Road	Eucalyptus scoparia	Canopy is 1 branch plus epicormic, insect infestation in over 50% of canopy, < 2 Years ULE
9.	118-122 Highbury Road	Eucalyptus scoparia	Declining canopy, 30% loss, unlikely to recover, < 2 Years ULE
10.	118-122 Highbury Road	Eucalyptus scoparia	Declining canopy, 30% loss, unlikely to recover, < 2 Years ULE
11.	118-122 Highbury Road	Eucalyptus scoparia	1m n/strip, epicormic canopy, multiple wounds in trunk, decay evident, < 2 Years ULE
12.	136 Highbury Road	Eucalyptus scoparia	Epicormic crown, insect infestation over 50% of canopy, canopy nearly dead, < 2 Years ULE
13.	144-160 Highbury Road	Eucalyptus scoparia	Declining canopy, disease attacking, < 2 Years ULE
14.	1/230 Highbury Road	Eucalyptus scoparia	Dead
15.	246 Highbury Road	Eucalyptus scoparia	Tree has been pruned poorly around power lines, canopy is all on north side and is declining, < 2 Years  ULE
16.	248 Highbury Road	Eucalyptus scoparia	tree has been pruned poorly around power lines, canopy is 2 declining branch on north side, < 2 Years ULE
17.	288 Highbury Road	Eucalyptus scoparia	Tree poorly pruned around power lines, branch obstructing street light to clear would leave no canopy, < 2 Years ULE
18.	314 Highbury Road	Eucalyptus scoparia	1.5m n/strip, crown epicormics, < 2 Years ULE
19.	204 Highbury Road	Hakea salicifolia	Tree is dead, fungal fruiting bodies at base, < 2 Years ULE
20.	294 Highbury Road	Eucalyptus scoparia	Poor form, 1m nature strip, < 2 Years ULE.

<sup>\*&</sup>lt; 2 Years ULE - a useful life expectancy of less than two years

The table below lists the details of the locations of trees to be planted in vacant sites along Highbury Road, Mount Waverley/Burwood.

No.	Street Location	16.	1/124 Highbury Road
1.	1. 361 Warrigal Road		1/130 Highbury Road
2.	2 Highbury Road	18.	144-160 Highbury Road
3.	3. 6 Highbury Road		144-160 Highbury Road
4.	1/8 Highbury Road		1 Lynn Street
5.	20 Highbury Road	21.	200 Highbury Road
6.	1 Barnes Avenue	22.	1/214 Highbury Road
7.	7. 1 Barnes Avenue		1/216 Highbury Road
8.	2 Barnes Avenue	24.	228 Highbury Road
9.	1/34 Highbury Road	25.	254 Highbury Road
10.	48-54 Highbury Road	26.	266 Highbury Road
11.	48-54 Highbury Road	27.	280-282 Highbury Road
12.	48-54 Highbury Road	28.	280-282 Highbury
13.	100-104 Highbury Road	No.	Street Location
14.	112 Highbury Road	29.	280-282 Highbury
No.	Street Location	30.	284 Highbury Road
15.	15. 114 Highbury Road		290 Highbury Road

32.	292 Highbury Road  298 Highbury Road  300 Highbury Road  1/304 Highbury Road  306 Highbury Road	
33.		
34.		
35.		
36.		
37.	1/308 Highbury Road	
38.	316 Highbury Road	
39.	1/320 Highbury Road	
40.	296 Highbury Road	

## MAP - Removals, Replacements & Infill Planting

The map below details the removals, replacements and infill plantings along Highbury Road, Mount Waverley/Burwood.









Legend				
	New Tree To be planted			
	Tree to be removed and replaced			
	Tree to be removed but not replaced			