

# Property Servicing Report

**Proposed Residential Development** 

**FMG REF:** S42623- 263744

**ISSUE DATE:** 24 May 2019

**SITE ADDRESS** 52 Golf Road, OAKLEIGH SOUTH, VIC 3167

CLIENT: VIMG Australia Pty Ltd

**Engineering** your success.

MELBOURNE SYDNEY Site: Ref

### © Koukourou Pty Ltd trading as FMG Engineering

The work carried out in the preparation of this document has been performed in accordance with the requirements of FMG Engineering's Quality Management System which is certified by a third party accredited auditor to comply with the requirements of ISO9001.

This document is and shall remain the property of FMG Engineering. The document is specific to the Client and site detailed in the document. Use of the document must be in accordance with the Terms of Engagement for the commission and any unauthorised use of this document in any form whatsoever is prohibited. No part of this document including the whole of same shall be used for any other purpose nor by any third party without the prior written consent of FMG Engineering.

FMG Engineering reserves the right to append, amend and / or modify the contents of this document upon receipt of additional information.

### **Document Status**

Rev	Author	Reviewer	Issue Date
0	Guy Harris Civil Engineer	Stephen Dunstone Vic Manager Buildings & Infrastructure	28 Nov. 18
1	Guy Harris Civil Engineer	Dipendra Sharma Civil Manager	7 Dec. 18
2	Guy Harris Civil Engineer	Dipendra Sharma Civil Manager	19 Dec. 18
3	Akhil Shrestha Civil Engineer	Stephen Dunstone Vic Manager Buildings & Infrastructure	24 May. 19

FMG Job Number: 263744 Revision:2 Date: 24 May. 19

# Table of contents

1.0 Introduction			
	1.1.	Project Reference Documents	5
2.0	Develo	opment Proposal	5
3.0	Engine	opment Proposaleering	6
		Site Topography	
	3.2.	Roads	6
	3.3.	Sewer	7
	3.4.	Water	8
	3.5.	Drainage	9
	3.6.	Comms	. 10
	3.7.	Gas	
	3.8.	Electricity	. 12

# 1.0 Introduction

FMG has been requested by VIMG to prepare a property servicing report for the proposed residential development at 52 Golf Road, Oakleigh South VIC 3167

This report has been structured to present an understanding of the delivery requirements for the development as identified in the location below.



This report will identify major utility infrastructure required to service the proposed development, and, is of a preliminary nature and has been prepared to identify key infrastructure required to be incorporated into the development or to be extended from existing utility assets.

This report outlines the infrastructure constraints and proposed mitigation measures, and, will demonstrate to the planning team that the proposed design considerations can meet VIMG and other authority guidelines taking into attention the following items:

- Stormwater
- Water, Sewer & Gas, and
- Power & Communications

This report represents the infrastructure design requirements needed for development purposes. Should design considerations or alteration to proposed master planning conditions occur, it is recommended a new report/study be undertaken to reflect the changes.

### 1.1. Project Reference Documents

The information contained in this report has been based on:

- Monash City Council
  - Road infrastructure
  - Stormwater
  - Open Space
- South East Water
  - Sewer
  - Potable Water
- **United Energy** 
  - Electricity
- **Multinet Gas** 
  - Gas
- **NBN** Co

# 2.0 Development Proposal

The site at 52 Golf Road, Oakleigh South is to be developed for a residential development. The total number of dwellings is expected to be 89 with a combination of 2, 3 and 4 bedroom townhouses. Development on the site will need to have regard and be compatible with council. The proposed development is identified below.




# 3.0 Engineering


FMG has completed a desktop assessment of the servicing availability of the subject site and found that there is not expected to be any major constraints on servicing a proposed townhouse development. This is due to the current use of the site, the flat topography and the access to main road frontage. The subject site is therefore considered a prime development site from an Infrastructure supply point of view.

Asset	Authority	Availability
3.1. Site Topography	vic.gov.au	The site has approximately 1.5m of fall from north-east to southeast which equates to a fall of approximately 1 in 140. This fall would support the development and would not likely result in the need for retaining walls and smart engineering solutions.  Such a slope would not impact the lot layout for the development but as the fall is relatively constant, we believe the slope would not be detrimental to the feasibility of the development if factored for as part of the urban design
3.2. Roads	Monash	Local road networks surrounding the site are owned and managed by City of Monash Council. It is assumed site access would be achieved from Golf Road.  All internal roads to the development would be constructed to council standard with ownership though a Body Corporate arrangement.


Asset	Authority	Availability
3.3. Sewer	South East Water	A 150mm diameter sewer exists in Beryl Avenue along the southern boundary of the site. The depth of this sewer should enable the development of the site to be controlled back to this point. The sewer drains run to the west towards Cameron Avenue.  It is assumed Sewer outfall can be provided with minimum external construction works due to proximity of existing sewer main. The capacity of this existing sewer needs to be confirmed with SEW prior to any development works.



Asset	Authority	Availability
3.6. Comm s	TELSTRA	It is assumed Telecommunications connection can be provided with some external construction works required as all Telstra pits are located on the opposite side of the road to the development.  Telecommunications assets exist surrounding the subject site along the western and southern boundary. It appears no telecommunications feed into the site. No reticulation of telecommunicators currently exist throughout the site
		5 5 6 100.64 7.7 22.5 30 18 5 100.64 7.7 25 30 100.64 7.7 25 30 10
		13.2 1.17  1
		0 459



# Asset Authority **Availability** Overhead LV electricity infrstucure exists along Golf Road and Beryl 3.8. Electricity Avenue. An overhead HV exists on Cameron avenue near the intersection of Beryl and Cameron Avenue. These assets are managed by United Energy UNITED ENERGY The existing electrical supply will not have the capaicty to service the proposed development. The existing LV pole at the intersection of Cameron and Beryl Avenue will need to be upgraded to a HV pole. A new pole on Golf Road for overhead supply from the new upgraded HV with undeground into a new kiosk. There will be a requirement for new infrastructure including main switchboards and distribution metering cabinets to service the density of the development proposed. Electrical availability will be confirmed when asset information is received from the responsible authority. 105 109 Ö SŦ BERYL 115 ΑV CAMERON-BERYL



# **ADELAIDE**

67 Greenhill Road Wayville SA 5034 Ph: 08 8363 6600

# MELBOURNE

2 Domville Ave Hawthorn VIC 3122 Ph: 03 9815 7600

# **SYDNEY**

Suite 28, 38 Ricketty S Mascot NSW 2020 Ph: 1300 975 878

ABN: 58 083 071 185