
The table below lists the details of the trees to be removed due to SSRIP works. Please refer to map below for replacement details.


No.	Street Address	Species	Condition Assessment
1.	22 Wellington Road	Melia azedarach	Removal due to SSRIP
2.	Opposite 1786-1788 Dandenong Road	Populus sp.	Removal due to SSRIP
3.	2-1764 Dandenong Road	Pyrus spp.	Removal due to SSRIP
4.	2-1764 Dandenong Rd in Browns Road	Pyrus spp	Removal due to SSRIP
5.	1/1-3 Seascape St. in Browns Road	Pyrus spp	Removal due to SSRIP
6.	2/1-3 Seascape St. in Browns Road	Pyrus spp.	Removal due to SSRIP
7.	6 Browns Road	Photinia spp.	Removal due to SSRIP
8.	6 Browns Road	Pyrus spp.	Removal due to SSRIP
9.	1 Browns Crt.	Pyrus spp.	Removal due to SSRIP
10.	1 Browns Crt.	Melaleuca spp	Removal due to SSRIP
11.	20 Browns Crt.	Melaleuca spp.	Removal due to SSRIP
12.	Fregon reserve frontage	Cupressus sempervirens	Removal due to SSRIP
13.	Fregon reserve frontage	Cupressus sempervirens	Removal due to SSRIP
14.	Fregon reserve frontage	Melaleuca spp.	Removal due to SSRIP
15.	Fregon reserve frontage	Cratageus spp.	Removal due to SSRIP
16.	Fregon reserve frontage	Pyrus spp.	Removal due to SSRIP
17.	Fregon reserve frontage	Corymbia ficifolia	Removal due to SSRIP
18.	Fregon reserve frontage	Cupressus sempervirens	Removal due to SSRIP
19.	In Fregon reserve (opposite 1/2 Atlantic St)	Eucalyptus spp (dead)	Removal due to SSRIP
20.	Monash Medical Centre carpark	Pyrus spp.	Removal due to SSRIP

21.	8-10 Browns Road	Corymbia spp.	Removal due to SSRIP
22.	8-10 Browns Road	Pyrus spp.	Removal due to SSRIP
23.	12 Browns Road	Cratageus spp.	Removal due to SSRIP
24.	14 Browns Road	Corymbia ficifolia	Removal due to SSRIP

MAP – Removals and Replacements – SSRIP

The map below details the removals and replacements for the SSRIP works.





Legend	
	New Tree To be planted
	Tree to be removed and replaced
	Tree to be removed but not replaced

The table below lists the details of the trees to be removed due to Street Tree Strategy works. Please refer to map below for replacement details.

1.	108 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
2.	96 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
3.	90 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
4.	86 Browns Road	Pinus halapensis	Healthy but very poor form. Remedial pruning cannot rectify.
5.	86 Browns Road	Crataegus sp.	40% of canopy dead, major failures, wounds and decay in trunk, < 2 Years ULE.
6.	80 Browns Road	Corymbia eximia 'Nana'	Declining health, poor form, < 2 Years ULE.
7.	78 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
8.	72 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
9.	70 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
10.	56 Browns Road	Corymbia ficifolia	Stressed, unlikely to recover, wounded trunk, < 2 Years ULE.
11.	54 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
12.	50 Browns Road	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
13.	48 Browns Road	Melaleuca styphelioides	Suppressed and unlikely to recover, < 2 Years ULE.
14.	44 Browns Road	Melaleuca styphelioides	Declining health, canopy sparse, 20% dieback, < 2 Years ULE.
15.	2/2 Seascape Street	Crataegus sp.	Declining. Little to no amenity, < 2 Years ULE.
16.	4/2 Seascape Street	Melaleuca styphelioides	Declining. Little to no amenity, < 2 Years ULE.
17.	1/2 Atlantic Street	Melaleuca styphelioides	Canopy declining, foliage small, 30% canopy thinning, < 2 Years ULE.
18.	1/1 Atlantic Street	Corymbia ficifolia	Codominant leaders. Will not develop into tree with good amenity, < 2 Years ULE.
19.	15A Browns Road	Melaleuca styphelioides	Canopy declining, foliage small, 30% canopy thinning, < 2 Years ULE.
20.	21C Browns Road	Eucalyptus leucoxylon	Declining. Little to no amenity, < 2 Years ULE.
21.	23A Browns Road	Melaleuca styphelioides	Declining health, 50% canopy loss, < 2 Years ULE.
22.	29 Browns Road	Melaleuca styphelioides	Declining health, 50% canopy loss, < 2 Years ULE.
23.	31-49 Browns Road	Pyrus calleryana 'Chanticleer'	inappropriate location under wire stay.
24.	31-49 Browns Road	Melaleuca styphelioides	Declining health, < 2 Years ULE>
25.	31-49 Browns Road	Corymbia ficifolia	Major wound with bracket fungi at base impacting health and structure, 25% canopy loss, < 2 Years ULE.


The table below lists the details of vacant site plantings in Browns Road.

NI -	Charact Address	
No.	Street Address	
1.	106 Browns Road	
2.	28 Browns Road	
3.	16 Browns Road	
4.	MONASH MEDICAL CENTRE CAR PARK 6C Browns Road	
5.	4 Browns Road	
6.	1/1-3 Seascape Street in Browns Road	
7.	2/2 Atlantic Street in Browns Road	
8.	2/1 Fortuna Street in Browns Road	
9.	2 Lantana Street in Browns Road	
10.	15-17 Browns Road	
11.	27 Browns Road	
12.	29 Browns Road	
13.	29 Browns Road	
14.	31-49 Browns Road	
15.	31-49 Browns Road	
16.	31-49 Browns Road	
17.	31-49 Browns Road	
18.	31-49 Browns Road	
19.	31-49 Browns Road	
20.	209-211 Carinish Road in Browns Road	
21.	209-211 Carinish Road in Browns Road	


*Fregon Reserve will be planted with between 6-10 vacant site plantings, dependant on final species chosen

MAP – Removals and Replacements – Street Tree Strategy


The map below details the removals and replacements for the Street Tree Strategy.



Legend	
	New Tree To be planted
	Tree to be removed and replaced
	Tree to be removed but not replaced



Legend	
	New Tree To be planted
	Tree to be removed and replaced
	Tree to be removed but not replaced



Legend	
	New Tree To be planted
	Tree to be removed and replaced
	Tree to be removed but not replaced

