Tree Removals.

The table below lists the details of the trees to be removed, including tree location, tree species and condition assessment. For replacement details, please refer to map below.

*< 2 Years ULE - with a useful life expectancy of less than two years

1.	Street Address	1/12 Marianne Way
	Species	Prunus cerasifera Nigra
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	
2.	Street Address	13 Marianne Way Mount Waverley Vic 3149
	Species	Agonis flexuosa
	Condition Assessment	*< 2 Years ULE, Declining health and not expected to
		recover, significant pest, disease or decay present
	Tree Image	

3.	Street Address	21 Marianne Way
5.	Species	Eucalyptus sp
	Condition Assessment	*< 2 Years ULE, Declining health and not expected to
	Condition Assessment	recover
	Tree Image	
4.	Street Address	38-40 Marianne Way
	Species	, Acacia longifolia
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	

5.	Street Address	39 Marianne Way
5.	Species	Prunus sp
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
	condition Assessment	present
	Tree Image	
6.	Street Address	43 Marianne Way
	Species	Corymbia ficifolia
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	

7.	Street Address	45 Marianne Way
7.	Species	Acer sp.
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
	Condition Assessment	present
	Tree Image	
8.	Street Address	74 Marianne Way
	Species	Prunus sp.
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	

9.	Street Address	76 Marianne Way
	Species	Prunus cerasifera Nigra
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	
10.	Street Address	2/86 Stephensons Road
	Species	Prunus cerasifera Nigra
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	

11.	Street Address	93 Marianne Way
	Species	Prunus cerasifera Nigra
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay
		present
	Tree Image	
12.	Street Address	106 Marianne Way
	Species	Agonis
	Condition Assessment	*< 2 Years ULE, Significant pest, disease or decay present
	Tree Image	


13.	Street Address	111 Marianne Way
	Species	Prunus & Sucker
	Condition Assessment	*< 2 Years ULE, Poor form and/or structure
	Tree Image	

The table below lists the details of the locations where trees will be planted in vacant sites along Marianne Way, Mount Waverley.

No.	Street Location	
1.	88 Stephensons Road Mount Waverley Vic 3149	
2.	7 Marianne Way Mount Waverley VIC 3149	
	*Tree scheduled for removal as part of Reactive Tree Works – as at 27-05-2019	
3.	31 Marianne Way Mount Waverley Vic 3149	
4.	35 Marianne Way Mount Waverley Vic 3149	
5.	38-40 Marianne Way Mount Waverley Vic 3149	
6.	1/27 Jacqueline Road Mount Waverley Vic 3149	
7.	91 Marianne Way Mount Waverley Vic 3149	
8.	92 Marianne Way Mount Waverley Vic 3149	
9.	100 Marianne Way Mount Waverley Vic 3149	
10.	102 Marianne Way Mount Waverley Vic 3149	
11.	117 Marianne Way Mount Waverley Vic 3149	

MAP - Removals, Replacements & Infill Planting

The map below details the removals, replacements and infill plantings. All other trees have been assessed as having more than 2 years useful life and will be retained.









Proposed Tree Species Options

Option 1 – Single species (both sides of the road)



Option 2 – Single species (both sides of the road)



Option 3 – Combination of species

