

Strelden Avenue, Huntingdale

The table below lists the details of the trees to be removed and the replacement trees at each location.

Location	Species	Condition Assessment
4 Strelden Avenue	<i>Prunus cerasifera Nigra</i>	Co dominance and trunk wounds, unlikely to mature, < 2 Years ULE*
1/12 Strelden Avenue	<i>Prunus cerasifera Nigra</i>	Has been lopped, undesirable branch development from stump, < 2 Years ULE*
1/36 Strelden Avenue	<i>Callistemon salignus</i>	Disease deforming foliage, 95% affected, < 2 Years ULE*
79 Clayton Road	<i>Prunus cerasifera Nigra</i>	Dieback throughout canopy, significant decay in crown union, < 2 Years ULE*

*< 2 Years ULE - with a useful life expectancy of less than two years



The table below lists the details of the locations where the selected tree species will be planted in a vacant site.

Street Location
1 Strelden Avenue
38 Tullius Avenue adjoining Strelden Avenue
55 Patrick Street adjoining Strelden Avenue
55 Patrick Street adjoining Strelden Avenue
29 Strelden Avenue
1/22 Strelden Avenue
28 Strelden Avenue
1/32 Strelden Avenue
1/40 Strelden Avenue

MAP - Removals, Replacements and Infill Planting

The map below details the removals, replacements and infill plantings. All other trees have been assessed as having more than 2 years useful life and will be retained.



Legend	
	New Tree To be planted
	Tree to be removed and replaced